

## KoamTac KDC300 Rev2.83 Upgrade Procedure

July 29, 2009

**WARNING: DO NOT REMOVE KDC300 from PC during FW UPDATE PROCESS until AFTER resetting the KDC300 unit as outlined below.**

1. Plug KDC300 into PC USB port
2. Check the KoamTac Data Collector COM port
  - Control Panel -> System -> Hardware -> Device Manager -> Ports
3. Execute KDC300\_V283.exe.
4. Click Step1 Select Serial Port and select the correct COM port
  - KDC300\_V283 program will search available COM ports and could take few minutes to search all available COM ports. DO NOT TOUCH PC during the COM port searching.
5. Click Step2 Check KDC300
6. Click Step3 Download new F/W. DO NOT REMOVE THE KDC300 until after the reset
7. Reset KDC300
  - Plug KDC300 USB connector to PC USB port.
  - Press lower menu button and scan button together for 5 seconds.
  - Release lower menu button and scan button once LED becomes yellow.
  - Initial screen ("KoamTac Data Collector KDC300") is displayed once reset.
  - KDC300 stores collected data into flash memory and wouldn't lose the data during reset process.
  - Press two side buttons
  - Go to System > Fac. Default; Select Yes & Exit; Exit Menu
  - Go to System > Reset Memory; Select Yes & Exit; Exit Menu



KoamTac, Inc.

support@koamtac.com